

## CERTIFICATION by CUSTODIAN of RECORDS

Tucson Police Department Crime Laboratory 1306 W. Miracle Mile, Tucson, AZ 85705

I hereby certify that these documents are a true and correct copy of the periodic maintenance* for the Intoxilyzer 8000 Serial Number  **P0-000334*  maintained by the Tucson Police Department Crime Laboratory pursuant to the requirements of the Arizona Department of Public Safety for a quality assurance program.			
A quality assurance specialist (QAS) tested the instrurdates. The acceptable accuracy limits, as defined in A. for a 0.100AC solution are 0.090AC to 0.110AC.	ment on the following A.C. R13-10-104.A.2,		
Date: 10/17/11	2_ <b>0.098</b> AC		
Between the dates of 9/15/11 and 1 the instrument was operating properly and accurately.	10/17/11		
The instrument was taken out of service for repair on  The instrument was returned to service on			
Sarah Cione			
Sarah L. Cione			
10/27/11			
ADPS QAS Permit # 33355			
SUBSCRIBED AND SWORN to before me this	<u>27</u> , day of		
An Hernander			
Notary Public	OFFICIAL SEAL  A.M. HERNÁNDEZ  NOTARY PUBLIC-ARIZONA		
*Includes documents specified in A.A.C. R13-10-104.A.5	PIMA COUNTY My Comm. Exp. Mar. 17, 2012		

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

#### EXHIBIT G-4

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

159

STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST Sarah Cione	AGENCY Tucson Police Department	
	TIME 1046	
INTOXILYZER SERIAL # 80-000334		
( $\checkmark$ ) 1. Display reads "PUSH BUTTON TO	START"	
DIAGNOSTIC TESTS		
( ) 1. Clock time check. ( ) 2. Date check.		
OPERATIONAL TESTS		
<ul> <li>1. Alcohol-free subject test result 0.000 AC.</li> <li>2. Error recognition logic system functioning.         Not a Successfully Completed Test Sequence printed</li> <li>3. Proper sample recognition system.         Not a Successfully Completed Test Sequence printed Deficient sample printed.</li> <li>4. Standard Calibration Check standard 0.100 AC Result: 0.098 AC</li> </ul>		
Instrument is operating properly and acc	curately. YESNO	
COMMENTS I day past due on Calibra	tion Check	
SIGNATURE Sarah Cion		

DPS Form Exh G-4 (Rev. 05-01)

Location: TUCSON POLICE DEPT

Serial Number: 80-000334

10/17/2011

10:47:31

Standard Lot#: 20910100A1 Last Changed By: S. CIONE

#50616

QAS: S. CIONE

#50616

TUCSON PD

Operator: S. CIONE

#50616

TUCSON PD

Subject: SQAP, SQAP DOB: 11/11/1111

Sex: F

Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	10:48:17
Diagnostic Test	Pass	10:48:44
Air Blank	0.000	10:49:11
0.100 Cal Check	0.098	10:49:30
Air Blank	0.000	10:50:00
Subject Test	0.000	10:50:26
Air Blank	0.000	10:50:54
Five Minute Wait	ABT*	
Air Blank	0.000	10:51:29

<sup>\*</sup>Sequence Aborted

## Not a Successfully Completed Test Sequence

Location: TUCSON POLICE DEPT

Serial Number: 80-000334

10/17/2011

10:51:54

Standard Lot#: 20910100A1

Last Changed By: S. CIONE

#50616

QAS: S. CIONE

#50616

TUCSON PD

Operator: S. CIONE

#50616

TUCSON PD

Subject: SQAP, SQAP

DOB: 11/11/1111

Sex: F

Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	RFI*	10:52:19
Air Blank	IPS**	10:52:27

<sup>\*</sup>RFI Detect

### Not a Successfully Completed Test Sequence

<sup>\*\*</sup>Improper Sample

Location: TUCSON POLICE DEPT Serial Number: 80-000334

10/17/2011

10:53:41

Standard Lot#: 20910100A1

Last Changed By: S. CIONE

#50616

QAS: S. CIONE

#50616

TUCSON PD

Operator: S. CIONE

#50616

TUCSON PD

Subject: SQAP, SQAP

DOB: 11/11/1111
Sex: F

Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	10:54:23
Diagnostic Test	Pass	10:54:51
Air Blank	0.000	10:55:18
0.100 Cal Check	0.099	10:55:37
Air Blank	0.000	10:56:07
Subject Test	0.064*	10:59:15
Air Blank	0.000	10:59:47
Air Blank	0.000	11:00:14
Subject Test	XXX**	11:00:52
Air Blank	0.000	11:01:26

<sup>\*</sup>Deficient Sample

Begin new deprivation period

## Not a Successfully Completed Test Sequence

<sup>\*\*</sup>Invalid Sample

Location: TUCSON POLICE DEPT Serial Number: 80-000334

10/17/2011

11:02:28

Standard Lot#: 20910100A1

Last Changed By: S. CIONE #50616

-----

-----

QAS: S. CIONE #50616

TUCSON PD

Test	g/210L	Time
Air Blank	0.000	11:02:55
Cal Check	0.098	11:03:14
Air Blank	0.000	11:03:43

Pursuant to section 28-1327. Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

#### EXHIBIT G-2

# THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

# STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

134 11.7-2011

STANDARD CALIBRATION CHECK PROCEDURE

QA Specia	elist <u>Sarah Cionl</u>	AGENCY Tucson Police Department
DATE 10/		
Intoxily	zer Serial # <u>80-000334</u>	Location DUI HQ
7		
(✔ ) 1	. Ensure that gas tank is att standard alcohol concentrat OR	tached to instrument and contains a zion solution 0.100 AC.
	into a clean dry simulator	concentration solution $AC$ , and assemble the simulator. Ensure an made. Turn on the simulator and $34^{\circ}C \pm 0.2^{\circ}C$
( <b>V</b> ) 2	. Intoxilyzer 8000 display	y reads "PUSH BUTTON TO START"
	. Go to the "Control Test	ting Menu". Select "D" for dry for wet control test. After
( <b>V</b> ) 4	. Air blank completed.	
		eted. Test results 0. 098 AC.
( v ) 6	<ul><li>Air blank completed.</li><li>Remove printed record.</li></ul>	
( ) 7	. Remove printed record. checklist.	Attach the record to the completed
SIGNATUR	E Sarah Cion	

DPS Form Exh G-2 (Rev. 05-01)

7 of 950

INTOXILYZER 8000

Location: TUCSON POLICE DEPT

Serial Number: 80-000334 10/17/2011

10:46:04

Standard Lot#: 20910100A1

Last Changed By: S. CIONE #50616

------

-----

QAS: S. CIONE #50616

TUCSON PD

Test	g/210L	Time
Air Blank	0.000	10:46:31
Cal Check	0.098	10:46:50
Air Blank	0.000	10:47:19

8 of 9 sc



# TUCSON POLICE DEPARTMENT CRIME LABORATORY

# INTOXILYZER SERVICE RECORD

754 11.2.201
Date: 10/17/11
QAS: Sarah Cione
Intoxilyzer Serial Number: 80 - 000334
Reason For Service: <u>During SQAP check</u> , breath hose felt + sounded like there was a leak. More difficult to do a breath test as breath sample seemed to be leaking out of breath hose. Still able to complete SQAP
Date Out of Service: $10/17/11$
Calibration Check completed prior to removal from service
Date: Did not remove from service
SQAP completed prior to removal from service
Date: Did not remove from service
Corrective Action: Sent to CMI, Inc.  Replaced breath hose. Completed a breath test successfully.

134

INTOXILYZER 8000 Location: TUCSON POLICE DEPT Serial Number: 80-300334 10/17/2011

13:59:09

Standard Lot#: 2091010001 Last Changed By: S. CICNE #50616

QAS: S. CIONE #50616 TUCSON PD

Operator: S. CIONE #50616 TUCSON PD

Subject: TEST,TEST DOB: 11/11/1111 Sex: F Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	13:59:59
Diagnostic Test	Pass	14:00:28
Air Blank	0.000	14:00:55
0.100 Cal Check	0.098	14:01:14
Air Blank	0.000	14:01:43
Subject Test	0.000	14:02:13
Air Blank	0.000	14:02:41
Five Minute Walt		
Air Blank	0.000	14:07:41
Subject Test	0.000	14:07:57
Air Blank	0.000	14:08:24
0.100 Cal Check	0.098	14:08:43
Air Blank	0.000	14:69:13
Diagnostic Test	Pass	14:09:42

Successfully Completed Test Sequence